Karnataka Fire and Emergency Services Department Office of the District fire officer.



Tumkur Fire station BH Road,Tumkur – 572, 103 Ph No 0816 – 2283101



Date: 18-12-2024.

No.191/CC/DFO/TFS/2024.

To,
The Authorized Signatory

M/s. Green Wood International School,
Benachigere Gate, NH-206,
Nittur Hobli, Gubbi Taluk,
Tumkur District-572216

Sir.

Sub : Issue of "Compliance report" with respect to fire prevention, fighting and

evacuation measures maintained at M/s. Green Wood International School, Benachigere Gate, NH-206, Nittur Hobali, Gubbi Taluk, Tumkur District-

572216

Ref : Fire Safety Recommendation C.No.191/FSR/DFO/TFS/2024.Dt:-18/12/2024.

* * * * * *

With reference to subject above cited, 'Fire Safety Recommendation' was issued wide reference (1) to the premises of M/s. Green Wood International School, Benachigere Gate, NH-206, Nittur Hobli, Gubbi Taluk, Tumkur District-572216. with a condition to fulfill the recommendations and compliance the same within 3 months.

The applicant has requested to this office for Issue of Compliance Certificate. In this regard 1 was inspected the premises on 07-12-2024 for issuing Compliance Certificate, the management M/s. Green Wood International School, Benachigere Gate, NH-206, Nittur Hobali, Gubbi Taluk, Tumkur District-572216. Was complied the all recommendation communicated in Fire Safety Recommendation except training part.

Under the above circumstances the Karnataka Fire & Emergency Services Department is issuing the 'Fire Safety Compliance Certificate' to M/s. Green Wood International School, Benachigere Gate, NH-206, Nittur Hobali, Gubbi Taluk, Tumkur District-572216. Subject to proper maintenance of firefighting systemsIn good working condition. And At least 40% of employees should be trained in basic firefighting course at our R.A.Mundkur Fire and Emergency Services Training Academy, Bannerghatta Road, Bangalore-29

This Fire Safety Compliance Certificate is Valid till 17-12-2025 and it is renewable.

District Fire Officer Karnataka Fire & Emergency Service

Tumakuru-572 103